

1/5




FIG 1

2/5




FIG 2





FIG 3

3/5



4/5





FIG 5

FIG 6



The diagram illustrates a three-dimensional coordinate system with axes labeled R (vertical), Z (horizontal), and X (depth). A curved surface is shown, with various points and regions labeled with identifiers:

- 26a: A label on the left side of the surface.
- 27a: A label on the upper left side of the surface.
- 14a: A label on the upper part of the surface.
- 20a: A label on the bottom left side of the surface.
- 46: A label on the bottom right side of the surface.
- 17: A label on the right side of the surface.
- 28a: A label on the far right side of the surface.

FIG 7

5/5




FIG 8




FIG 9